AMMONIA TRANSFER OPERATION

MANDATORY PPE DURING THE TRANSFER OPERATION

SAFETY GOGGLES

TYPE K RESPIRATOR

PROTECTIVE GLOVES

CHEMICAL PROTECTIVE SUIT

SAFETY BOOTS

SAFETY HELMET WITH CHIN STRAP

CORROSIVE

HARMFUL/IRRITANT

INSTRUCTIONS

1 BEFORE THE TRANSFER

- **Check the identity of the product.**
- **Check that the delivered quantity does not exceed the tank capacity : 35 mS (< 30 t).**
- **Establish the safety perimeter and restrict access.**
- **Verify that the emergency safety shower is operational.**
- Connect the ground terminal to the truck.
- Connect the tanker truck gaseous sky to the storage tank's one.

2 DURING THE TRANSFER

- **The unloading supervisor must be present at all times.**
- Monitor the transfer operation continuously.

  (If any abnormality occurs: stop the operation immediately and notify your supervisor)

3 AFTER THE TRANSFER

- Disconnect grounding connection and gaseous sky.
- Put the padlocks back on.
- Ensure the area is clean before leaving, and only depart after approval from the unloading supervisor.

IN CASE OF FIRE OR ACCIDENTAL SPILL

Call the Control Room at **05.57.35.16.90**

Remove contaminated clothing.

Rinse the affected area with water.

Inform site personnel and seek medical attention.

IN CASE OF AN ACCIDENTAL SPILL

If the spilled quantity is small, dilute it with plenty of water.

NO SMOKING OR VAPING

MORE INFORMATIONS
MOP, FDS, FSU...
Scan me!