MINSORB TRANSFER OPERATION

MANDATORY PPE DURING THE TRANSFER OPERATION

SAFETY GOGGLES

FFP3 RESPIRATOR

PROTECTIVE GLOVES

CHEMICAL PROTECTIVE SUIT

SAFETY BOOTS

SAFETY HELMET WITH CHIN STRAP

INSTRUCTIONS

1 BEFORE THE TRANSFER

- **Check the identity of the product.**
- **Check that the silo has sufficient capacity to receive the delivered quantity : 37,5 mS (< 30 t).**
- **Establish the safety perimeter and restrict access.**
- Remove the safety barrier and the valve cap.

2 DURING THE TRANSFER

- **The unloading supervisor must be present at all times.**
- Monitor the transfer operation continuously.
  (If any abnormality occurs: stop the operation immediately and notify your supervisor)

3 AFTER THE TRANSFER

- Reinstall the safety barrier and the valve cap.
- Ensure the area is clean before leaving, and only depart after approval from the unloading supervisor.

IN CASE OF FIRE OR ACCIDENTAL SPILL

Call the Control Room at **05.57.35.16.90**

Remove contaminated clothing.

Rinse the affected area with water.

Inform site personnel and seek medical attention.

IN CASE OF AN ACCIDENTAL SPILL

If the spilled quantity is small, dilute it with plenty of water.

NO SMOKING OR VAPING

MORE INFORMATIONS
MOP, FDS, FSU...
Scan me!